

**National Transportation Safety Board
Washington, DC 20594**

Brief of Accident

Adopted 12/08/1998

DCA96MA079							
File No. 1724		09/05/1996		NEWBURGH, NY		Aircraft Reg No. N68055	
						Time (Local): 05:54 EDT	
Make/Model: McDonnell Douglas / DC-10-10CF						Fatal	
Engine Make/Model: GE / CF6-6D						Serious	
Aircraft Damage: Destroyed						Minor/None	
Number of Engines: 3						Crew	
Operating Certificate(s): Flag Carrier/Domestic						Pass	
Type of Flight Operation: Non-scheduled; Domestic; Cargo						0	
Reg. Flight Conducted Under: Part 121: Air Carrier						0	
Last Depart. Point: MEMPHIS , TN						Condition of Light: Dawn	
Destination: BOSTON , MA						Weather Info Src: Weather Observation Facility	
Airport Proximity: On Airport						Basic Weather: Instrument Conditions	
Airport Name: NEWBURGH/STEWART INTL						Lowest Ceiling: 3000 Ft. AGL, Broken	
Runway Identification: 27						Visibility: 2.00 SM	
Runway Length/Width (Ft): 11818 / 150						Wind Dir/Speed: 280 / 004 Kts	
Runway Surface: Asphalt						Temperature (°C): 18	
Runway Surface Condition: Dry						Precip/Obscuration:	
Pilot-in-Command		Age: 47				Flight Time (Hours)	
Certificate(s)/Rating(s)						Total All Aircraft: 12344	
Airline Transport; Commercial; Multi-engine Land; Single-engine Land						Last 90 Days: Unk/Nr	
Instrument Ratings						Total Make/Model: 2504	
Airplane						Total Instrument Time: UnK/Nr	

The airplane was at FL 330 when the flightcrew determined that there was smoke in the cabin cargo compartment. An emergency was declared and the flight diverted to Newburgh/Stewart International Airport and landed. The airplane was destroyed by fire after landing. The fire had burned for about 4 hours after after smoke was first detected. Investigation revealed that the deepest and most severe heat and fire damage occurred in and around container 6R, which contained a DNA synthesizer containing flammable liquids. More of 6R's structure was consumed than of any other container, and it was the only container that exhibited severe floor damage. Further, 6R was the only container to exhibit heat damage on its bottom surface, and the area below container 6R showed the most extensive evidence of scorching of the composite flooring material. However, there was insufficient reliable evidence to reach a conclusion as to where the fire originated. The presence of flammable chemicals in the DNA synthesizer was wholly unintended and unknown to the preparer of the package and shipper. The captain did not adequately manage his crew resources when he failed to call for checklists or to monitor and facilitate the accomplishment of required checklist items. The Department of Transportation hazardous materials regulations do not adequately address the need for hazardous materials information on file at a carrier to be quickly retrievable in a format useful to emergency responders.

Brief of Accident (Continued)

DCA96MA079

File No. 1724

09/05/1996

NEWBURGH, NY

Aircraft Reg No. N68055

Time (Local): 05:54 EDT

Occurrence #1: FIRE
Phase of Operation: CRUISE

Findings

1. (C) CARGO/BAGGAGE - SMOKE
2. (C) CARGO/BAGGAGE - FIRE
3. (C) CARGO/BAGGAGE - UNDETERMINED
4. SUPERVISION - INADEQUATE - PILOT IN COMMAND
5. HAZARDOUS MATERIAL
6. INFORMATION INSUFFICIENT - OTHER GOVERNMENT PERSONNEL

Occurrence #2: FORCED LANDING
Phase of Operation: EMERGENCY LANDING

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.
an in-flight cargo fire of undetermined origin. (NTSB Report AAR-98/03)